

Replacement Sheet




FIG. 1




FIG. 2

Replacement Sheet




FIG. 3




FIG. 4

Replacement Sheet




FIG. 5

Replacement Sheet




FIG. 6

Replacement Sheet




FIG. 7A




FIG. 7B

Replacement Sheet




FIG. 8

Replacement Sheet




FIG. 9

Replacement Sheet




FIG. 10 PRIOR ART




FIG. 11

Replacement Sheet




FIG. 12A




FIG. 12B

Replacement Sheet




FIG. 13

Replacement Sheet




FIG. 14

Replacement Sheet





FIG. 15

Replacement Sheet**FIG. 16**

Replacement Sheet




FIG. 17A

Replacement Sheet




FIG. 17B

Replacement Sheet





FIG. 18

Replacement Sheet


RECEIVED
CENTRAL FAX CENTER

SEP 21 2006




TUNNEL DIODE

FIG. 19A PRIOR ART



SCHOTTKY DIODE

FIG. 19B PRIOR ART



BACK TUNNEL DIODE

FIG. 19C PRIOR ART